

Amendments to the Specification

Please replace the paragraph that begins on page 7, line 15 with the following amended paragraph:

When the prime door is closed, weather seal **55** presses against a substantially continuous and coplanar sealing surface ~~[[25]]~~ formed by main frame member **21**, threshold **23**, and the hinge assemblies **80**. As best seen in Figures 6 and 10, the main frame member **21** has an outwardly extending rib **35** with an outwardly facing surface **215** which is one of the main parts of this continuous sealing surface. The threshold **23** has a similar outwardly facing surface **235**. As may be seen in Figures 2, surfaces **215** and **235** are substantially coplanar, and are substantially parallel to the outer and inner skins **43**, **45** of the door when the door is closed.

Please replace the paragraph that begins on page 9, line 18 with the following amended paragraph:

As best seen in Figure 7, the fixed hinge leaf has three knuckles **811** for a hinge pin **91**. These knuckles are separated by two notches: a smaller notch **814** for the prime hinge leaf **83** and a larger notch **815** for the screen hinge leaf **85**. The prime hinge leaf and screen hinge leaf have similar knuckles (**831** and **851** respectively), partially cut away to accommodate acetal plastic hinge bushings **87**, which are inserted into the top of the bores **825** in the fixed hinge leaf knuckles **811** and the bottom of the bores **845**, ~~[[855]]~~ **856** in the prime hinge leaf knuckle **831** and screen hinge leaf bushing **851**. Hinge pin **91** extends through the bushings, through plugs **89** in each knuckle, one of which is illustrated in the cut-away portion of the screen leaf bushing in Figure 7, and through a washer **93** beneath the lowest fixed hinged bushing. The lower end **91** of the hinge pin is swedged to provide a secure assembly. With the positive location afforded by the notches in the weather seal rib **217**, the hinge assemblies lend themselves to removal of an entire door and/or replacement of an individual hinge, if damaged through negligence.